

VEHICLE INSPECTION REPORT

MA56239

KRONE CURTAINSIDE EUROLINER

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	Colour	BLUE	Axle Combi	Tri
Year	VIN	WKESD000000682160	Rear Suspension	Air
Mileage	Body Style	Trailer	Rear Doors	Barn
Fuel Type	Brakes	Drum		

NOT REGISTERED IN THE UK BPW AXLES, RAISE & LOWER VALVE, FERRY LASHINGS, SLIDING ROOF

Tyres

NSF
NSR
OSF
OSR
Spare