

VEHICLE INSPECTION REPORT

MA56047

KRONE CURTAINSIDE EUROLINER

Inspection

Vehicle

VAT

V5 N/A

Details

Reg. date

Colour

Axle Combi

Tri

Year

VIN

WKESD000000681276

Rear Suspension

Air

Mileage

TBC

Body Style

Trailer

Rear Doors

Barn

Fuel Type

Brakes

Drum

NOT REGISTERED IN THE UK BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS, SLIDING ROOF, ENXL RATED HEADBOARD

Tyres

NSF

NSR

OSF

OSR

Spare