

VEHICLE INSPECTION REPORT

BG72ENV

Ford Transit Custom 300 2.0 ECOBLUE 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/09/2022

Year 2022

Mileage 24,824 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYNU65419

Body Style Panel Van L1

MOT Due 21/09/2025

CAP Clean £11,300.00

CAP Average £10,450.00

CAP Below £8,975.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR,

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Door nsf
Dented
Over 30mm



4: Door nsf
Dented
Over 30mm



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Dented
Over 30mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



11: Door nsr
Dented
With Paint Damage



12: Seat Base Cover osf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		