

VEHICLE INSPECTION REPORT

YS20BGY

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 28/07/2020

Year 2020

Mileage 112,560 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTREL27417

Body Style Panel Van L2

MOT Due Expired

CAP Clean £5,000.00

CAP Average £4,475.00

CAP Below £3,675.00

Gearbox MANUAL

Gears 6

SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



2: Door Moulding nsr
Scuffed (Unpainted)
UpTo 100mm



3: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



4: Qtr Panel Trim ns
Scuffed
Over 25mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK