

# VEHICLE INSPECTION REPORT

**YS20BVL**

## Ford Transit 350 2.0 ECO BLUE 130PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 28/07/2020

Year 2020

Mileage 97,012 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTREL18174

Body Style Panel Van L2

MOT Due 30/05/2026

CAP Clean £5,750.00

CAP Average £5,100.00

CAP Below £4,200.00

Gearbox MANUAL

Gears 6

### SIDE LOADING DOOR

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



2: Door Moulding nsf  
Scuffed (Unpainted)  
UpTo 100mm



3: Door Moulding nsr  
Scuffed (Unpainted)  
Over 100mm



4: Qtr Panel Trim os  
Scuffed  
Over 25mm

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK