

VEHICLE INSPECTION REPORT

Vehicle

Cab Type

Gearbox

YK17VOH

DAF LF 230

Inspection

Fuel Type

Colour

| | | VAI | Plus VA I | _ | | |
|-----------|----------------------|------------|-------------------|-----------------|--------|--|
| | | V5 | Present | - | | |
| Details | | | | | | |
| Reg. date | 11/05/2017 | VIN | XLRAEL2700L463660 | Axle Combi | 4x2 | |
| Year | 2017 | Body Style | Flatbed | Rear Suspension | Steel | |
| Mileage | 198,747 Km Warranted | MOT Due | 28/02/2026 | Tail Lift | Column | |

DAY CAB

AUTOMATIC

BOTTLE CHASIS, SURROUND CAMERA SYSTEM

Diesel

WHITE

| Tyres NSF | | | |
|--------------|--|--|--|
| NSR | | | |
| OSF | | | |
| OSR | | | |
| Spare | | | |

Features

Park assist camera
Air conditioning

Photos













