

VEHICLE INSPECTION REPORT

PE68VPN

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 23/10/2018

Colour BLUE

Cab Type DAY CAB

Year 2018

VIN XLRAEL3700L471909

Gearbox MANUAL

Mileage 381,840 Km Warranted

Body Style Beavertail

Axle Combi 4x2

Fuel Type Diesel

MOT Due 31/10/2025

Rear Suspension Air

WINCH, SURROUND CAMERA SYSTEM, WEIGH SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4


Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Park assist camera
- Cloth seat trim
- Digital radio


Photos







Condition Check



Damage Photos

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		