

VEHICLE INSPECTION REPORT

C313859

DON BUR CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2011	Colour	RED	Axle Combi	Tri
Year	2011	VIN	SEPBV38FXBL058013	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Roller
Fuel Type		Brakes	Drum		

ROPES, REAR AXLE & FLOOR REQUIRE ATTENTION BPW AXLES, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



