

VEHICLE INSPECTION REPORT

FJ65VXW

Daf LF 250

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Reg. date	25/11/2015	Body Style	Curtainside	Axle Combi	4x2
Year	2015	Keys	1	Steering Combi	Steer
Mileage	498,329 Km Not Warranted	MOT Due	30/11/2025	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Barn
Colour	WHITE	Gearbox	Automatic		
VIN	XLRAEL3700L447614	Doors	2		

* NON RUNNER DOESNT START OR DRIVE ENGINE PARTIALLY STRIPPED * FORKLIFT BRACKET


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing osf
Scratched
Over 25mm Thru Paint



4: Door osf
Dented
Over 30mm



5: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel osr
Cracked
Replace



7: Tailgate
Rusted
Over 5mm



8: Bumper Rear Moulding
Missing
Replace



9: Qtr Panel nsr
Hole
Over 10mm

10: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs		Fault	Gearbox 1st and Reverse Test	Fault
Brakes		Fault	Clutch Slip Test from Static	Fault
Parking Brake		Fault	Gearbox Static Gear Selection (engine running)	Fault
			No Excessive Smoking	Fault
EML light illuminated		Fault	Oil warning light illuminated	Fault
Airbag light illuminated		Fault	DPF light illuminated	Fault
ABS light illuminated		Fault	Service indicator light illuminated	Fault
Windows		OK	Radio	OK