

VEHICLE INSPECTION REPORT

BL15YBU

Iveco Daily 70-170 4100WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 22/06/2015

VIN ZCFC270C305012195

CAP Below £4,075.00

Year 2015

Body Style Panel Van

Gearbox MANUAL

Mileage 88,878 Miles
Warranted

Keys 1

Doors 2

Fuel Type Diesel

CAP Clean £6,875.00

Steering Combi Standard Axle

Colour WHITE

CAP Average £5,625.00

Rear Suspension Steel

PENNY SWING LIFT, INVERTER, COMPRESSOR, ELECTRIC CABLE REEL

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Multiple Chips



2: Wing osf
Dented
With Paint Damage



3: Bonnet
Rusted
Over 5mm



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door osr
Dented
With Paint Damage



6: Qtr Panel osr
Rusted
Over 5mm

Interior

Carpet Condition	Poor
Seat Condition	Poor

Upholstery Condition	Poor
Odour	No