

VEHICLE INSPECTION REPORT

WV68WFD

Ford Transit Custom 300 2.0 TDCi 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 28/09/2018

Year 2018

Mileage 140,844 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYJU29006

Body Style Crew Van L1

MOT Due 21/01/2026

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, TOW BAR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Door Pad nsr
Broken
Replace



2: Seat Base Cover nsr
Soiled
Heavy



3: Seat Back Cover nr
Soiled
Heavy



4: Seat Back Cover nr
Soiled
Heavy



5: Seat Base Cover nr
Soiled
Heavy



6: Seat Back Cover osr
Soiled
Heavy



7: Seat Base Cover osr
Soiled
Heavy



8: Carpets Rear
Soiled
Heavy



9: Door Pad osf
Scuffed
Over 25mm



10: Seat Base Cover osf
Soiled
Heavy



11: Seat Base Cover nsf
Soiled
Heavy



12: Seat Base Cover nsf
Soiled
Heavy



13: Fascia Panel
Scuffed
Over 25mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	Yes
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		