VEHICLE INSPECTION REPORT

HS68VEO


Carr Hill

Ford Transit Connect 240 1.5 Tdci Base

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	31/01/2019	Colour	White	MOT Due	07/01/2026
Year	2019	VIN	WF0SXXWPGSJG60254	Gearbox	MANUAL
Mileage	143,448 Miles Warranted	Body Style	Panel Van LWB	Gears	5
		Keys	1	Doors	2
Fuel Type	Diesel				


^{*} LIVINGSTON * SINGLE SIDE DOOR, ELECTRIC WINDOWS, REMOTE CENTRAL LOCKING

Tyres NSF NSR OSF Spare





Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Door osf Dented Over 2 UpTo 10mm

No Image

No Image

3: Bumper Rear Moulding Scuffed (Unpainted) Over 100mm





5: Door nsf Chipped 1 To 5



6: Door nsf Chipped 1 To 5

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Mechanical Inspection

Important Notice: Customer must satisfy themselves that the health check is as stated by 5pm day after sale and prior to leaving centre. If vehicle has been delivered we must be notified within two hours of arrival at your dealership.

EML light illuminated	Fault
Airbag light illuminated	Fault
ABS light illuminated	Fault