

VEHICLE INSPECTION REPORT

YS67POF

Ford Transit Connect 220 1.5 Tdci

Non Runner
Inspection

Conditions		Vehicle	
Outdoors - Good light		VAT	Plus VAT
Serious Damage?	No	V5	Buyer To Apply

Details

Reg. date	18/12/2017	Colour	White	Gearbox	MANUAL
Year	2017	VIN	WF0RXXWPGRHD64778	Gears	5
Mileage	128,567 Miles Not Warranted	Body Style	Panel Van SWB	Doors	2
Fuel Type	Diesel	Keys	1		

NON RUNNER - DOES NOT START SINGLE SIDE DOOR


Tyres


NSF
NSR
OSF
OSR
Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 30mm



2: Door nsr
Rusted
Over 5mm



3: Bonnet
Chipped
Multiple Chips



4: Wing osf
Chipped
Multiple Chips



5: Door osf
Dented
Over 30mm



6: Qtr Panel osr
Dented
Over 30mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No