

# VEHICLE INSPECTION REPORT

**PG66UEL**

## Daf CF 440

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 22/02/2017

VIN XLRTGM4100G147522

Cab Type SLEEPER CAB

Year 2017

Body Style Tractor Unit

Gearbox AUTOMATIC

Mileage 1,348,321 Km  
Warranted

Service history Yes

Axle Combi 6x2

Service documents Printout

Steering Combi Mid-Lift Steer

Fuel Type Diesel

MOT Due 31/12/2025

Rear Suspension Air

Colour RED

\*COLLECTED AS NON RUNNER - TURBO/ WIRING FAULTS\*

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

## Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

## Photos












Condition Check



Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Fascia Panel  
Missing  
Replace

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		