

VEHICLE INSPECTION REPORT

SK700SP

Ford Ranger THUNDER 2.0 ECOBLUE 213PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	15/09/2020	Body Style	Pickup Double Cab	Gearbox	AUTOMATIC
Year	2020	Keys	2	Gears	1
Mileage	53,904 Miles Not Warranted	MOT Due	14/09/2025	Axle Combi	4x4
Fuel Type	Diesel	CAP Clean	£13,950.00	Rear Suspension	Steel
Colour	GREY	CAP Average	£12,450.00		
VIN	6FPPXXMJ2PLD16216	CAP Below	£10,200.00		

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Navigation system
- USB/iPod interface
- Drivers airbag
- Cruise control
- Park assist camera
- Air conditioning
- Passenger airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Central locking
- Heated front seat
- Radio/CD
- Rear electric windows
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Sill os
Scratched
UpTo 25mm Not Thru Paint



2: Bonnet
Dented
Over 2 UpTo 10mm



3: Door osf
Dented
Over 2 UpTo 10mm



4: Tailgate
Scratched
UpTo 25mm Not Thru Paint



5: Door nsf
Chipped
Edge Chip

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK