

VEHICLE INSPECTION REPORT

C19MKM

IVECO STRALIS 310

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 12/02/2018

Year 2018

Mileage 243,447 Km Not Warranted

Fuel Type DIESEL

Colour YELLOW

VIN WJME62RNX0C385867

Body Style Dropside & Crane

MOT Due 31/07/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Rear Steer

Rear Suspension Air

WARNING LIGHT ON DASH, MOT HISTORY IN MILES & KMS ATLAS 135.2VE REMOTE CRANE (YEAR 2018), REAR LIFT, LAST CRANE TEST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Not Thru Paint



3: Door nsf
 Scratched
 Over 25mm Not Thru Paint



4: Door nsf
 Scratched
 Over 25mm Not Thru Paint



5: Wing nsf
 Scratched
 Over 25mm Thru Paint



6: Wing osf
 Chipped
 Multiple Chips

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		