

VEHICLE INSPECTION REPORT

CF74BZH

Vauxhall Combo 1.5 TURBO D 100PS PRIME

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/11/2024

Year 2024

Mileage 4,861 Miles Not Warranted

Fuel Type DIESEL

Colour WHITE

VIN W0VEDYHT8RJ946514

Body Style Panel Van SWB

MOT Due 29/11/2027

CAP Clean £13,550.00

CAP Average £13,050.00

CAP Below £11,700.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



2: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		