

VEHICLE INSPECTION REPORT

NX67NGZ

Iveco Daily 3.0 50-150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	29/09/2017	Body Style	Tipper Double Cab	Gearbox	MANUAL
Year	2017	Service history	Yes	Axle Combi	4x2
Mileage	175,830 Km Warranted	MOT Due	31/10/2025	Rear Suspension	Steel
Fuel Type	Diesel	CAP Clean	£4,575.00	Rear Doors	Barn
Colour	WHITE	CAP Average	£3,850.00	Tail Lift	Column
VIN	ZCFC150B905140133	CAP Below	£2,950.00		

WEIGH SYSTEM, STEEL BODY TIPING GEAR, 3750WB

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos










Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Cracked
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Dented
With Paint Damage



7: Headlamp ns
Broken
Replace



8: Tailgate Trim Panel
Broken
Replace



9: Door osf
Dented
With Paint Damage



10: Wing osf
Dented
With Paint Damage




11: Door Mirror Assy osf
Broken
Replace



12: Screen Front
Scratched
Over 30mm



13: Door Pad osr
Soiled
Heavy



14: Carpets Rear
Soiled
Heavy



15: Seat Base Cover osr
Soiled
Heavy



16: Door Pad nsr
Soiled
Heavy



17: Seat Base Cover nsf
Soiled
Heavy



18: Door Pad osf
Soiled
Heavy



19: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	