

VEHICLE INSPECTION REPORT

DL21NVF

Vauxhall Movano 3500 2.3 Turbo D 135ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/05/2021

Year 2021

Mileage 34,200 Miles
Warranted

Fuel Type Diesel

Colour SILVER

VIN W0VMR8609MB257509

Body Style Welfare Van

Service history Yes

Service documents Printout

MOT Due 08/06/2026

CAP Clean £8,875.00

CAP Average £8,075.00

CAP Below £6,800.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, E/MIRRORS, MICROWAVE, WATER BOILER, SINK, 240V SOCKETS

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Bluetooth connection
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking
- Auxiliary input socket
- Metallic Paint
- Cloth seat trim
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bonnet
Chipped
Multiple Chips



5: Badgedecal Front
Broken
Replace



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Fuel Flap
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Qtr Panel Moulding ns
Missing
Replace



15: Bumper Rear Moulding
Broken
Replace



16: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		