

VEHICLE INSPECTION REPORT

GN64TPO

MERCEDES-BENZ ACTROS

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	02/09/2014	VIN	WDB9634232L891607	Axle Combi	6x2
Year	2014	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	Not Showing	MOT Due	Expired	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.3M, FLAT FLOOR)		
Colour	WHITE	Gearbox	AUTOMATIC		

NON RUNNER - DOES NOT POWER UP SLIDING 5TH WHEEL

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Air conditioning

Photos





