

VEHICLE INSPECTION REPORT

YS19MTU

Ford Ranger WILDTRAK 200 3.2 TDCi

| Inspection | | Vehicle | | | |
|-----------------|-------------------------------|-------------|-------------------|-----------|-----------|
| Serious Damage? | No | VAT | Plus VAT | | |
| | | V5 | Buyer To Apply | | |
| Details | | | | | |
| Reg. date | 01/03/2019 | VIN | 6FPPXXMJ2PJR44232 | CAP Below | £7,600.00 |
| Year | 2019 | Body Style | Pickup Double Cab | Gearbox | AUTOMATIC |
| Mileage | 90,544 Miles Not Warranted | MOT Due | Expired | Gears | 6 |
| | | CAP Clean | £10,850.00 | | |
| Fuel Type | DIESEL | CAP Average | £9,475.00 | | |
| Colour | GREY | | · | | |

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, TOW BAR, E/MIRRORS, HEATED WINDSCREEN

| Tyres | | | |
|--------------|--|--|--|
| Tyres NSF | | | |
| NSR | | | |
| OSF | | | |
| OSR | | | |
| Spare | | | |

Features


- Bluetooth connection
- Navigation system
- Mobile phone App interface
- Air conditioning
- · Drivers airbag
- Cruise control
- Park assist camera
- Radio/CD
- Front electric windows
- Passenger airbag
- Front parking sensor
- Rear parking sensor Radio/CD Multichanger
- Rear electric windows
- Central locking
- · Heated front seat
- Digital radio LED headlights
- Metallic Paint
- · Partial leather seat trim


Photos
















Condition Check



Damage Photos



1: Door nsf Dented With Paint Damage



2: Door nsf Chipped Edge Chip



3: Door nsf Chipped Edge Chip



4: Door nsr Chipped Over 5mm

Interior

| Carpet Condition | OK | | Upholstery Condition | OK | |
|--------------------------|----|-----|------------------------------|-------------------------|-------|
| Seat Condition | OK | | Odour | No | |
| Engine Runs | | OK | Gearbox 1st and Revers | e Test | OK |
| Brakes | | OK | Clutch Slip Test from Sta | ntic | OK |
| Turbo Boosting | | OK | Gearbox Static Gear Sel | ection (engine running) | OK |
| Parking Brake | | OK | No Excessive Smoking | | OK |
| EML light illuminated | | OK | Oil warning light illuminate | ted | Fault |
| Airbag light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | Service indicator light illu | minated | OK |
| AAE or all access | | 01/ | Desilia | | OK |
| Windows | | OK | Radio | | OK |
| Sat nav | | OK | Steering | | OK |