

VEHICLE INSPECTION REPORT

KU18DYS

MERCEDES-BENZ ANTOS 2545

Inspection	Vehicle

VAI	Plus VA I
V5	To Follow

Details

Reg. date	01/05/2018	VIN	WDB96302020212319	Rear Suspension	Air
Year	2018	Body Style	Fridge Box	Rear Doors	Barn
Mileage	462,842 Km Warranted	Cab Type	DAY CAB	Tail Lift	Column
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	6x2		

FRIGOBLOCK UNIT, STANDBY PLUG, REAR LIFT, SURROUND CAMERA SYSTEM

I	У	res	
---	---	-----	--

NSF

NSR

OSF

OSR

Spare

Features

· Park assist camera

· Air conditioning

Photos













