

VEHICLE INSPECTION REPORT

C338796

DON BUR BOX DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	02/03/2013	Colour	RED	Brakes	Disc
Year	2013	VIN	SEPBV38GHDL060757	Axle Combi	Tri
Mileage	TBC	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	03/11/2025	Rear Doors	Roller

CORROSION BPW AXLES

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



