

# VEHICLE INSPECTION REPORT

**SJ67LFF**

## Iveco Daily 35-140 2.3 3750WB

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	03/10/2017	Body Style	Tipper Double Cab	Gearbox	AUTOMATIC
Year	2017	Keys	2	Gears	6
Mileage	39,757 Miles Warranted	MOT Due	01/09/2025	Doors	4
Fuel Type	Diesel	CAP Clean	£10,200.00	Steering Combi	Standard Axle
Colour	WHITE	CAP Average	£8,625.00	Rear Suspension	Steel
VIN	ZCFCD35AX05175050	CAP Below	£6,550.00	Tail Lift	Column

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm



2: Bumper Front  
Cracked  
Over 25mm



3: Wing osf  
Dented  
With Paint Damage



4: Door osf  
Dented  
With Paint Damage



5: Door osr  
Dented  
Over 30mm



6: Qtr Panel osr  
Dented  
With Paint Damage



7: Tailgate  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Bumper Front  
Hole  
Over 25mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK