

VEHICLE INSPECTION REPORT

BU68LMK

Mercedes-Benz Citan 109 CDI Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

nama
GRADE
3

Details

Reg. date 21/12/2018

Year 2018

Mileage 34,183 Miles Not Warranted

Fuel Type Diesel

Colour White

VIN WDF4156032U256236

Body Style Panel Van LWB

CAP Clean £4,525.00

CAP Average £3,900.00

CAP Below £3,050.00

Gearbox MANUAL

SIDE LOAD DOOR, E/WINDOWS & MIRRORS, REAR VIEW CAMERA

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera

Photos






Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips



Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	Yes

Mechanical Inspection

Important Notice: Customer must satisfy themselves that the health check is as stated by 5pm day after sale and prior to leaving centre. If vehicle has been delivered we must be notified within two hours of arrival at your dealership.

Service indicator light illuminated	OK
-------------------------------------	----