

VEHICLE INSPECTION REPORT

SJ67LFN

Iveco Daily 2.3 35-140 3750WB

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying
V5 Present

Details

Reg. date	03/10/2017	VIN	ZCFCD35A105176796	CAP Average	£7,200.00
Year	2017	Body Style	Tipper Double Cab	CAP Below	£5,475.00
Mileage	76,807 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	28/01/2026	Gears	6
Colour	WHITE	CAP Clean	£8,475.00	Rear Suspension	Steel

BRIT TIPP BODY, WEIGHER

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Wing osf
Dented
With Paint Damage



3: Door osf
Dented
With Paint Damage



4: Qtr Panel osr
Dented
With Paint Damage



5: Tailgate
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsf
Dented
With Paint Damage



8: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	