

VEHICLE INSPECTION REPORT

BU68LMM

Mercedes-Benz Citan 109 CDI Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

nama
GRADE
1

Details

Reg. date	21/12/2018	Colour	White	CAP Average	£2,675.00
Year	2018	VIN	WDF4156032U257405	CAP Below	£2,075.00
Mileage	100,371 Miles Not Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	Diesel	CAP Clean	£3,100.00		

SIDE LOADING DOOR, E/WINDOWS, TOW BAR *WARNING LIGHT ON DASH*

Tyres

NSF

NSR

OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Qtr Panel osr
Chipped
1 To 5



2: Qtr Panel nsr
Scratched
UpTo 25mm Not Thru Paint

Interior

Carpet Condition	OK
Seat Condition	OK

Upholstery Condition	OK
Odour	Yes

Mechanical Inspection

Important Notice: Customer must satisfy themselves that the health check is as stated by 5pm day after sale and prior to leaving centre. If vehicle has been delivered we must be notified within two hours of arrival at your dealership.

EML light illuminated	Fault	Service indicator light illuminated	Fault
-----------------------	-------	-------------------------------------	-------