

VEHICLE INSPECTION REPORT

BU68ZCF

Ford Transit Connect 200 1.5 TDCi 100ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/09/2018

Year 2018

Mileage 136,461 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRJS51419

Body Style Panel Van L1

MOT Due 10/10/2025

CAP Clean £2,850.00

CAP Average £2,450.00

CAP Below £1,925.00

Gearbox MANUAL

Gears 5

SIDE LOADING DOOR, AD BLUE

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos



Condition Check



Damage Photos



1: Wing nsf
Dented
Between 10mm + 30mm



2: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



3: Door nsf
 Scratched
 UpTo 25mm Thru Paint



4: Door Mirror Assy osf
 Scuffed (Unpainted)
 UpTo 100mm

Interior

| | | | |
|--------------------------|----|--|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | OK | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |