

VEHICLE INSPECTION REPORT

YM65TTE

Ford Fiesta 1.5 TDCi

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 27/01/2016

Year 2016

Mileage 54,744 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXGAKRFK51832

Body Style Car Derived Van

MOT Due Expired

CAP Clean £1,950.00

CAP Average £1,600.00

CAP Below £1,200.00

Gearbox MANUAL

Gears 5

WARNING LIGHTS ON DASH E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault