

VEHICLE INSPECTION REPORT

PJ18AUC

Daf CF 260

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	08/06/2018	VIN	XLRAEM3700G207385	Rear Suspension	Air
Year	2018	Body Style	Curtainside	Rear Doors	Barn
Mileage	426,408 Km Not Warranted	Cab Type	SPACE CAB	Tail Lift	Tuckaway
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	4x2		

STARTS ONLY, ENGINE & GEAR BOX ISSUES, HALF SHAFT REMOVED

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel nsr
Hole
Over 10mm



5: Unclassified
Major Parts Missing
Report Only



6: Bumper Front Moulding
Missing
Replace



7: Bumper Front Moulding
Missing
Replace



8: Door Pad osf
Broken
Replace



9: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpets Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs		Fault	