

VEHICLE INSPECTION REPORT

PE65VFB

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/12/2015

Year 2015

Mileage 1,398,927 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G087371

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/10/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON RUNNER - TYRE/ BRAKE, AIR BAG ISSUE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4



Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Qtr Panel Moulding ns
Broken
Replace



4: Qtr Panel Moulding ns
Broken
Replace



5: Panel Rear
Dented
With Paint Damage



6: Door osf
Dented
Over 30mm



7: Door osf
Dented
With Paint Damage



8: Door osf
Scratched
Over 25mm Thru Paint



9: Door osf
Rusted
Over 5mm



10: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



12: Screen Front
Chipped
Over 10mm



13: Door Pad osf
Broken
Replace



14: Fascia Panel
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		