

# VEHICLE INSPECTION REPORT

**RX63ATO**

## DAF LF 55.220

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | Present  |

### Details

|           |                     |            |                   |                 |         |
|-----------|---------------------|------------|-------------------|-----------------|---------|
| Reg. date | 10/09/2013          | Colour     | WHITE             | Cab Type        | DAY CAB |
| Year      | 2013                | VIN        | XLRAE55GF0L427400 | Gearbox         | MANUAL  |
| Mileage   | 63,637 Km Warranted | Body Style | Demount chassis   | Axle Combi      | 4x2     |
| Fuel Type | Diesel              | MOT Due    | Expired           | Rear Suspension | Steel   |

\*MAJOR OIL LEAK - STARTS & RUNS, WARNING LIGHTS ON DASH, MOT HISTORY INCORRECTLY RECORDED IN MILES/KM\*, ECON GRITTER BODY (YEAR 2013), SHEETING SYSTEM, PLOUGH

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features

- Park assist camera

## Photos





