

VEHICLE INSPECTION REPORT

DK17KYP

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 28/03/2017

Colour BLUE

Cab Type DAY CAB

Year 2017

VIN WMAN08ZZ5HY354375

Gearbox MANUAL

Mileage 257,536 Km Warranted

Body Style Dropside & Crane

Axle Combi 4x2

Fuel Type Diesel

MOT Due 31/01/2026

Rear Suspension Steel

WARNING LIGHT ON DASH HMF 1420-K2 REMOTE CRANE (YEAR 2016), SERVICE SCHEDULE LIST AVAILABLE


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Dented
Over 30mm



5: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
With Paint Damage



8: Wing osf
Cracked
Replace



9: Seat Base Cover osf
Holed
Over 3mm



10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		