Axle Combi

Rear Suspension



VEHICLE INSPECTION REPORT

242,533 Km Warranted Body Style

Vehicle

MOT Due

C291657

Iveco Stralis 460

Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	07/07/2014	Colour	WHITE	Cab Type	HI-WAY CAB
Year	2014	VIN	W.IMM1VTH60C291657	Gearbox	ALITOMATIC

Tractor Unit

30/09/2025

MOD654 FORM T/F, SLIDING 5TH WHEEL

DIESEL

Tyres

Mileage

Fuel Type

Inspection

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

Photos







4x2

Air





















Condition Check



Damage Photos







2: Bumper Front Chipped 1 To 5

Interior

Carpet ConditionOKUpholstery ConditionOKSeat ConditionOKOdour-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK