

VEHICLE INSPECTION REPORT

EN24RRZ

Volkswagen Crafter CR35 COMMERCE PLUS 2.0 TDI 140PS

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	24/07/2024	VIN	WV1ZZZSY2R9062308	CAP Below	£17,550.00
Year	2024	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	52,019 Miles Not Warranted	MOT Due	23/07/2027	Gears	6
		CAP Clean	£20,350.00		
Fuel Type	Diesel	CAP Average	£19,550.00		
Colour	WHITE				

^{*}WARNING LIGHTS ON DASH* SIDE LOADING DOOR, AD BLUE

Tyres			
Tyres NSF			
NSR	,		
OSF			
OSR			
Spare			

Features

- Front parking sensorFront electric windows
- Park assist camera
- · Rear parking sensor
- · Air conditioning

Photos

















Condition Check



Damage Photos



1: Bumper Front Scratched UpTo 25mm Thru Paint



2: Door Qtr Light nsf Cracked Replace



3: Bumper Front Grill Broken Replace



4: Bumper Front Insecure Action Required



5: Door Mirror Assy osf Broken Replace

Interior

Carpet Condition Seat Condition	OK OK		Upholstery Condition OK Odour No	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running	g) OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK