

VEHICLE INSPECTION REPORT

CU65BHK

Ford Transit 350 2.2 TDCi 155ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 04/11/2015

Year 2015

Mileage 115,039 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXFT31967

Body Style Panel Van L2

MOT Due 03/11/2025

CAP Clean £3,050.00

CAP Average £2,500.00

CAP Below £1,800.00

Gearbox MANUAL

Gears 6

*WARNING LIGHTS ON DASH*SIDE LOAD DOOR, TOW BAR, DEADLOCKS (WITH KEY)

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Number Plate Front
Broken
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Door osf
Dented
Over 30mm



7: Screen Front
Chipped
Over 10mm



8: Door Pad osf
Soiled
Heavy



9: Seat Base Cover osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy



11: Seat Base Cover nsf
Soiled
Heavy



12: Fascia Panel
Soiled
Heavy



13: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs		OK	No Excessive Smoking
OK		OK	
EML light illuminated		Fault	DPF light illuminated
OK		OK	
ABS light illuminated		OK	