

VEHICLE INSPECTION REPORT

CC70VER

SCANIA OMNI INTERLINK

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply

Details

Reg. date	30/09/2020	Colour	WHITE	MOT Due	03/10/2025
Year	2020	VIN	YS2K4X20001914971	Axle Combi	4x2
Mileage	362,151 Km Not Warranted	Body Style	Coach	Steering Combi	Standard Axle
Fuel Type	Diesel	Keys	1	Rear Suspension	Air

5% BUYERS FEE *WARNING LIGHTS ON DASH* 53 SEATS + DRIVER & CREW SEAT, PSVAR COMPLAINT, CONTINENTAL SIDE DOOR, WHEELCHAIR LIFT, TOILET, REAR EMERGENCY EXIT, FABRIC SEATS, 3 PT SEATBELTS, FULL WIDTH UNDERBODY STORAGE, OVERHEAD STOWAGE, MEDIA & ENTERTAINMENT SYSTEM, KNEEL FUNCTION

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- USB/iPod interface
- Cruise control
- Air conditioning
- Park assist camera
- Drivers airbag
- Radio/CD
- Partial leather seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Qtr Panel osr
Dented
With Paint Damage



3: Tailgate
Dented
With Paint Damage



4: Bumper Rear
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	

Windows

OK

Radio

OK

Steering

OK