

VEHICLE INSPECTION REPORT

CE20AWU

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/04/2020

Year 2020

Mileage 8,029 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL2700L489947

Body Style Sweeper

MOT Due Expired

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

STOCK BODY, 1,438 SWEEPER HOURS

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Digital radio
- Central locking
- Radio/CD
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Grille Front
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK