

VEHICLE INSPECTION REPORT

C598829

KRONE CURTAINSIDE COIL LINER

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | N/A |

Details

| | | | | | |
|-----------|------------|------------|-------------------|-----------------|------|
| Reg. date | 01/03/2023 | Colour | | Brakes | Drum |
| Year | 2023 | VIN | WKESD000001107971 | Axle Combi | Tri |
| Mileage | TBC | Body Style | Trailer | Rear Suspension | Air |
| Fuel Type | | MOT Due | 31/03/2026 | Rear Doors | Barn |

BPW AXLES, ALLOY WHEELS, IMPROVED SLIDING ROOF, FRONT LIFT AXLE, RAISE & LOWER VALVE, FERRY LASHING RINGS, ENXL RATED HEADBOARD, ENXL RATED CURTAINS, COIL WELL

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





