

VEHICLE INSPECTION REPORT

YN19KZH

Kia Niro 3 1.6 Gdi

Serious Damage

Inspection

Serious Damage? Yes

Vehicle

VAT Margin
V5 To Follow

Details

| | | | | | |
|-----------|-----------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 27/03/2019 | Colour | Blue | CAP Average | £7,225.00 |
| Year | 2019 | VIN | KNACC81CVK5268407 | CAP Below | £6,225.00 |
| Mileage | 106,463 Miles Not Warranted | Body Style | Estate | Gearbox | AUTOMATIC |
| Fuel Type | Hybrid Electric | CAP Clean | £8,175.00 | | |

ACCIDENT DAMAGE - MAY OR MAY NOT APPEAR ON VCAR HEATED SEATS

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Central locking
- Cruise control
- Auxiliary input socket
- Rear electric windows
- Leather seat trim
- Front parking sensor
- Digital radio
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag

Photos










Condition Check



Damage Photos



1: Bonnet
Cracked
Replace



2: Wing nsf
Missing
Replace



3: Wheel nsf
Damaged
Replace



4: Headlamp ns
Missing
Replace



5: Bumper Front Grill
Missing
Replace



6: Bumper Front
Missing
Replace



7: Sill Panel Trim ns
Broken
Replace



8: Bumper Rear
Dented
With Paint Damage



9: Qtr Panel osr
Scratched
Rusted

Interior

| | | | |
|-------------------------|---------|-----------------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition | Average | Odour | No |