

VEHICLE INSPECTION REPORT

2635102

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	03/08/2015	VIN	ZCFA675BX02635102	Axle Combi	4x2
Year	2015	Body Style	Box Van	Rear Suspension	Steel
Mileage	123,039 Km Warranted	MOT Due	31/12/2025	Rear Doors	Roller
Fuel Type	DIESEL	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	MANUAL		

MOD 654 FORM T/F, SINGLE SIDE DOOR

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
UpTo 25mm Thru Paint



2: Other
N/A
N/A



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Screen Front
Chipped
UpTo 10mm



5: Bumper Rear
Rusted
Over 5mm



6: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Other
N/A
N/A



9: Other
N/A
N/A

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK