

# VEHICLE INSPECTION REPORT

**A161669**

## Volvo B9R PLAXTON PANTHER

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date	06/05/2013	Colour	WHITE	Cab Type	DAY CAB
Year	2013	VIN	YV3S5P722DA161669	Gearbox	AUTO
Mileage	211,063 Km Warranted	Body Style	Coach	Axle Combi	4x2
Fuel Type	DIESEL	MOT Due	01/11/2025	Rear Suspension	Air

\*5% BUYERS FEE, FOR SALE TENDER ENDING 12 NOON 09/09/2025\* 53 SEATS + DRIVER, RECLINING FABRIC SEATS WITH FOOTRESTS, 3 PT SEATBELTS, OVERHEAD STOWAGE , REAR EMERGENCY EXIT, FULL WIDTH UNDER BODY STORAGE, \*MOD 654 FORM T/F\*

### Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Radio/CD
- Cruise control
- Air conditioning
- Park assist camera
- Cloth seat trim
- Auxiliary input socket


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Door Mirror Assy nsf  
Broken  
Replace




3: Wing nsf  
Scratched  
Over 25mm Thru Paint




4: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



6: B Post ns  
Scratched  
Over 25mm Not Thru Paint



7: B Post ns  
Cracked  
Replace



8: B Post os  
Cracked  
Replace



9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** OK  
**Odour** -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		