

VEHICLE INSPECTION REPORT

BX58JNJ

Ford Transit 350 2.4TDCI 115PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/01/2009

VIN WF0XXXBDFX8L27479

Gearbox MANUAL

Year 2009

Body Style Access Platform

Gears 6

Mileage 112,626 Km Warranted

Service history Yes

Axle Combi 4x2

Fuel Type Diesel

Service documents Printout

Rear Suspension Steel

Colour WHITE

Cab Type DAY CAB

COLLECTED AS NON RUNNER - VARIOUS ISSUES, NO ACCESS TO REAR

Tyres

NSF

NSR

OSF


OSR


Spare

Features

- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	Fault

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		