

VEHICLE INSPECTION REPORT

PE17HSU

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 14/03/2017

Year 2017

Mileage 1,517,440 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G150835

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/01/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

COLLECTED AS NON RUNNER- EGR VALVE ISSUES

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Number Plate Front
Missing
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Door osf
Dented
Over 30mm



8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		