

# VEHICLE INSPECTION REPORT

**PK65WDT**

## Iveco Daily 72-170

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 27/11/2015

Colour WHITE

Cab Type DAY CAB

Year 2015

VIN ZCFC170C305044146

Gearbox AUTOMATIC

Mileage 52,035 Km Warranted

Body Style Dropside

Axle Combi 4x2

Fuel Type DIESEL

MOT Due 30/11/2025

Rear Suspension Steel

### Tyres

NSF NSI1

NSI2 NSI3

NSI4

OSF OSI1

OSI2 OSI3

OSI4

Spare NSO1

NSO2 NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

## Features

- Park assist camera


## Photos







## Condition Check



## Damage Photos



1: Moulding on Wing  
Scuffed (Unpainted)  
Up To 100mm



2: Bonnet  
Chipped  
Multiple Chips





3: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



4: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



5: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



6: Bumper Rear  
Rusted  
Over 5mm



7: Other  
N/A  
N/A

## Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	