

# VEHICLE INSPECTION REPORT

**MA68NBN**

## Ford Transit 350 2.0 TDCi 130ps FWD

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 26/11/2018

Year 2018

Mileage 120,893 Miles Not Warranted

Fuel Type Diesel

Colour White

VIN WF0XXXTTGXJM57590

Body Style Panel Van L3

MOT Due 02/12/2025

CAP Clean £4,500.00

CAP Average £3,875.00

CAP Below £3,025.00

Gearbox MANUAL

SIDE LOADING DOOR, TOW BAR

### Tyres

NSF

NSR

OSF

OSR



Spare

## Features

- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Door Mirror Glass ns  
Broken  
Replace



3: Door nsf  
Chipped  
Multiple Chips



4: Door nsr  
Dented  
Over 30mm




5: Sill ns  
Dented  
Over 30% Of Panel



6: Panel Rear  
Dented  
Over 30mm



7: Qtr Panel osr  
Dented



8: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



9: Door Mirror Glass os  
Broken  
Replace

**Interior**

<b>Carpet Condition</b>	-	<b>Upholstery Condition</b>	-
<b>Seat Condition</b>	-	<b>Odour</b>	-