

VEHICLE INSPECTION REPORT

PJ68PXA

Iveco Daily 35-120 2.3 3520 WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/01/2019

Year 2019

Mileage 121,658 Miles Not Warranted

Fuel Type Diesel

Colour White

VIN ZCFC1358605254298

Body Style Panel Van MWB

MOT Due 11/02/2026

CAP Clean £4,500.00

CAP Average £3,950.00

CAP Below £3,175.00

Gearbox MANUAL

BEDFORD SIDE LOADING DOOR, TOW BAR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Scratched
UpTo 25mm Thru Paint



3: Door Window nsf
Cracked
Replace



4: Door nsf
Chipped
Multiple Chips



5: Door nsr
Chipped
Multiple Chips



6: Panel Rear
Missing
Replace



7: Qtr Panel osr
Dented
Over 30mm



8: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
Yes