



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DE67UJK

Daf CF 370

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	14/12/2017	VIN	XLRASM4100G176891	Rear Suspension	Air
Year	2017	Body Style	Fridge Box	Rear Doors	Roller
Mileage	465,442 Km Warranted	Cab Type	SLEEPER CAB	Tail Lift	Tuckaway
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	6x2		

REAR DOOR INOP CARRIER SUPRA 850MT UNIT, STANDBY PLUG, TWIN EVAP, SEPARATOR, REAR LIFT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking

Photos










Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door nsf
Dented
With Paint Damage



5: Badgedecal Front
Broken
Replace



6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Trim ns
Broken
Replace



8: Door osf
Dented
With Paint Damage



9: Qtr Panel Trim os
Broken
Replace



10: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		