

VEHICLE INSPECTION REPORT

SJ67LFM

Iveco Daily 35-140 2.3 3750WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/10/2017

Year 2017

Mileage 74,760 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCD35A205176466

Body Style Tipper Double Cab

Keys 2

MOT Due 02/10/2025

CAP Clean £8,400.00

CAP Average £7,125.00

CAP Below £5,425.00

Cab Type CREW CAB

Gearbox AUTOMATIC

Gears 6

Axle Combi 4x2

Rear Suspension Steel

BRITT TIP BODY, WEIGHER

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wing osf
Dented
Over 30mm



5: Door osf
Dented
Over 30mm



6: Qtr Panel osr
Dented
With Paint Damage



7: Tailgate
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsf
Dented
Over 30mm



10: Wing nsf
Dented
With Paint Damage



11: Door Mirror Assy nsf
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	

Windows

OK

Radio

OK

Steering

OK