

VEHICLE INSPECTION REPORT

DK17KYA

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	30/05/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ1HY357564	Gearbox	MANUAL
Mileage	197,209 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/11/2025	Rear Suspension	Steel

HMF 1420K RC REMOTE CRANE (2 EXT), C/W KINSHOFER BRICK GRAB, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Thru Paint



3: B Post ns
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Chipped
Multiple Chips



5: Lamp osr
Broken
Replace



6: B Post os
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Wing osf
Chipped
Multiple Chips



9: Bumper Front
 Scratched
 Over 100mm Thru Paint



10: Door Pad osf
 Broken
 Replace



11: Seat Base Cover osf
 Holed
 Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		